

D. JOHN PETER FIIV
INSURANCE SURVEYOR & LOSS ASSESSOR
VALUER

License No.SLA/52066/95
Valid upto: 10-07-2026

Cell No.98480 – 37582
Res: 27057583

H No.12-1-777,
Shanti Nagar,
North Lalaguda,
Near Water Tank,
Secunderabad-500 017.

Ref. No.JP/SBI/ AP39BK9257 /2025

Date : 04/04/2026

VALUATION REPORT
TO WHOMSOEVER IT MAY CONCERN

I, the undersigned had carefully inspected the below given vehicle and hereby give my report towards its present condition and Market Value :-

Registration No.	:	AP39BK9257
Date of Regn.	:	19/07//2019
Registered Owner/ Proposed Buyer	:	PILLI POTURAJU
Ownership Serial No	:	1
Chassis No:	:	MDHBDAN17J7602776
Engine No:	:	K9KE424/E051610
HPA/Lease if any	:	STATE BANK OF INDIA
ODA Meter Reading	:	136191KM
Make / Model	:	NISSAN SUNNY DCI XV BSIV
Class of Vehicle	:	MOTOR CAR
Colour	:	NIGHTSHADE2
Fuel	:	DIESEL
Condition of the Vehicle	:	Fair condition.
Clutch & Gear Box	:	Fair condition
Steering Linkages	:	Fair condition
Amount Paid	:	-

Valid Upto : -

F.C.No . : -

Valid Upto : 11/07/2034

Permit No. : -



Valid upto	:	-
 Insurance Particulars		
Original Insurance Policy Seen	:	No
Insurer	:	-
Tyres	:	All the tyres are about 30%
 <u>Battery</u>		
Make	:	AMARON
Condition	:	Fair condition
 <u>Body</u>		
Condition of the Body	:	Fair condition.
<u>Condition of the Mechanical Units</u>		
<u>Brake System</u>		
Whether Air/Hydraulic Brake etc	:	Fair condition.
Condition of the same	:	Fair condition.
Transmission / Axle / Suspension	:	Fair condition.
Engine Condition	:	Fair condition.
Condition of the same	:	Fair condition.
Last Major repair under taken	:	No
Market Value	:	3,30,000/-
Realizable Value	:	3,00,000/-
Distressed Value	:	2,70,000/-
General Comments	:	Vehicle is in Fair condition.

Remarks


Please Note:-

1. There above mentioned value would be vary basing on the document validly.
2. There are minor dents and scratches all over the body.
3. There are many discount schemes available on new vehicles.
4. The values of second hand vehicles is in down ward trend.
5. GST on vehicle is reduced.
6. Dicky assy is dent and deshaped.
7. Front bumper, rear bumper and dicky crome are broken and damaged.
- 8, All body panel are dented.

(D. JOHN PETER)

Surveyor & Loss Assessor
Valuer





భారతీయ స్టేట్ బ్యాంక్, రాజమహేంద్రవరం
भारतीय स्टेट बैंक, राजमहेंद्रवरम
STATE BANK OF INDIA, RASMEH & SARC, RJVM

12 MAY 2026 (20)

టాకా ముట్టినది/డాకా పొంది

DAK RECEIVED

D. JOHN PETER FIIV
INSURANCE SURVEYOR & LOSS ASSESSOR
No. SLA/52066/95
PAN No. AFEPD6030J
A/C No: 10243582838
Bank : SBI
Branch :Lalaguda
IFSC Code : SBIN0007112

Cell No.98480 - 37582
Res: 27057583
H.No. 12-1-777,
Shanti Nagar,
North Lallaguda,
Near Water Tank,
Secunderabad - 17.

PROFESSIONAL FEE BILL

Date : 04/04/2026		
Bill No. : SBI/ AP39BK9257		
To THE MANAGER STATE BANK OF INDIA		
Policy No.		
INSURED / OWNER PILLI POTURAJU Reg No / AP39BK9257		
	Rs.	Ps.
Professional Fee	3000	00
Traveling Expenses		
Halting Allowance		
Photographs 15 x 16 Nos		
Lodge Bills (Enclosed)		
Others		
Total	3000	00

(D. JOHN PETER)

Surveyor & Loss Assessor
Valuer

PLEASE REMIT THE VALUATION FEE TO ABOVE MENTIONED A/C ONLY.

L. J. Ramakrishna

