

S.K. SAXENA Surveyor & Loss Assessor		
License No. SLA No. 12455 Exp Date : 13-03-2028 SBI Ref.		109, Khari Kaun Rampur, (U.P.) 244901 Mon. No. 08279792291 Email : sksaxena0508@gmail.com
Assets Valuation Report For consideration of State Bank Of India, Main Branch Rampur		
Report No. :: SKS/APR/02 Bank Request Ref. No.	Dated 08-04-2026	Dated :08-04-2026 Requested By :: Branch Manager SBI,MB, Rampur
1	Borrower	
2	Reg. Owner	SONIYA d/o SHRI BHOOKAN LAL
3	Sr. No.	
INSPECTION DETAILS		
1	Date & Time of Inspection	08-04-2026
2	Place of Valuation of Inspection	Rampur
3	Valuation for Funding	Rs, 9,80,000
4	Valuation for Sale	Rs. 9,50,000
VEHICLE PARTICULARS		
1	Registration No.	UP -22BA-6076
2	Date of Registration	23-10-2023
3	RTO	RAMPUR
4	Dealer from Whom Purchased	MAHALAXMI MOTORS, BAREILLY
5	Name of the Manufacture	MAHINDRA SCORPIO CLASSICS11MT 7S CC BS6
6	Month & Year of Mfg.	09/ 2023
7	Vehicle Age	2 YEARS 6 MONTHS
8	Make / Model	06/ 2022
9	Chassis No.	MA1TA2YS2P2J20084
10	Engine No.	YSP4J67804
11	Class of Vehicle & Type of Body	MOTOR CAR /HARD TOP
12	Colour of the Vehicle	NEPOLI BLACK
13	Seating Capacity	7
14	Carrying Capacity	
	RLW	2510 KG
	ULW	1787 KG
15	Type of Fuel	DIESEL
16	Hypothecation effective Since	S TATE BANK OF INDIA, RAMPUR,
17	Average Collection per Daye	(U P)
	Verification	
FITNESS / PERMIT / ROAD TAX DETAILS		
1	Fitness Valid Upto	22-10-2038
2	Permit No.	
3	Nature of Permit	
4	Permit Valid Upto	
5	Permit Holder Name	
6	Route of Permit	
7	Tax Token Paid upto	One Time

MAJOR ACCESSORIES..... RATING A : GOOD, B: AVERAGE, C : POOR, D : ACCIDENTAL		
1	Interior	A- GOOD
2.	Load Body	Hard Top
3.	Chassis	Good
4	Engine	Start on trial
5	Suspension	Good
	(Front Suspension / Rear Suspension)	Good
6	Transmission / STG System	Good
7	Battery	Battery Good
8	Odometer Reading	90462 Km
9	Mechanical Condition	Average
10	Paint Work	Average
11	Steering Mechanism	Yes
	(Steering Wheel / Steering Box / Steering Shaft / Column / Steering Linkages)	
12	Electrical System	Yes
13	Axle Transmission System	Yes
	(PR Axle / Gear Box / Propeller Shaft / Differential Housing Axle)	
14	Cooling System	Yes
	Radiator	Yes
15	Exhaust System	No
	(Silencer / Manifold)	No
16	Brake System	Yes
	(Brake Pedal / Brake Piped)	
17	Others	Front Glass Crack, LH side Back Light Damage
	(Wheel Discs)	
	Tyres	Right Side
		Left Side
		Front :: 90 %
		Rear :: 35 %
	Original Records Verified	YES
	If this Vehicle is recently inspected by the same / any other valuer.	Yes
		No
	Reason of Valuation	If yes, Details
	Is this Vehicle Migrated from other area	
	Is it Re-Registered Vehicle :	
	Old Registration No.	
	Duplicate RC / Original RC	Original RC Present
	Is this a seized vehicle of Financiers	SBI, Main Branch, Rampur
	Name of the Financier	
	Over All condition of the Vehicle	

INSURANCE		
1.	Insurer	
2	Policy No. / Cover Note	
3.	Valid Upto	
4	Insured's Declared Value	
5.	Hypothecation if Any	STATE BANK OF INDIA, RAMPUR
6	Any Major Repairs undertaken in the last 2 years.	NO
VALUATION		
1	Invoice Value of New Vehicle	As per Invoice - Nil

	Present Market Value	Rs. 9,80,000/-
PENCIL IMPRESSION		
1	ODO Meter	90462 KM
2.	Regn. No. Plate	Yes
3.	Frame	Yes
4	Front	Yes
5	Side	Yes
6	Interior	Yes
Based on physical inspection / Condition of the Vehicle as describe in this Valuation Report, The Market value as on the date is Rs. 9,80,000(Nine Lakh Eighty Thousand Only, Reliable Value as on date in Rs 9,50,000/ Nine Lakh Fifty Thousand only.		
I hereby declare that ::		
a) The information furnished is true & correct to the best of my knowledge & belief. b) I have physically inspected the chassis No. & Engine No. Marked on the Vehicle, Along with the equipments and accessories fitted in the Vehicle. c) I have no direct or indirect interest in the vehicle valued. d) The vehicle is in a road worthy condition. e) This Valuation / Inspected is hereby given for Vehicle Loan Purpose only it is at the sole discretion of the Bank / Financier to accept or reject the proposal.		
PLACE AT WHICH VALUATION WAS DONE : Nawab Gate, Rampur DATE OF VALUATION :: 08-04-2026 DATE REPORT ISSUANCE : 13-04-2026		(Signature) S.K. Saxena

S.K. Saxena Surveyor & Co.
SLA No. 12455/Exp. 13/03/2028
SKA/UIIA-20/2024
Motor Engineers Marine, Loss
Assessor & Valuers
Email: sksaxena0508@gmail.com
#REF!

ADDRESS
109, Khari Kuan,
Rampur (UP) 244901
Mob. 8279792291

DATE	13.04.2026
------	------------

PRE RECEIPTED FEE BILL

Br. Manager
State Bank of India,
Main Branch, Rampur

OWNER	Ms. Soniya D/o Shri Bhookan Lal 256,Shahabad Road, Ajeetpur Choraha,Vill &PO Ajeetpur Rampur (Uttar Pradesh) Pin. 244901
--------------	--

VEHICLE NO	UP22BA6076
INSPECTION DATE	08.04.2026

Professional Fee			3000.00
D.A - Day			
T.A - Shivapuram, Rampur	10	Kms	145.00
@Rs.14.50/Km	1	Visit	
Digital Photo Graphs @ Rs.15.00 &Total Photo Prints	6	Nos	90.00
			3235.00
ADD:GSTIN@18%	0%		0.00
	0%		0.00
	Total Rs.		3235.00

RUPEES THREE THOUSAND TWO HUNDRED THIRTY FIVE ONLY

(S.K. SAXENA)

BANK A/C DETAILS :
A/C NO 2199101011368
IFSC CODE CNRB000219
CANARA BANK RAMPUR

