



GOVERNMENT OF ODISHA

[JHARSUGUDA RTO]

VEHICLE PARTICULARS



Application No: OR240416V2363494 Registration No: OD23Q7634
Registration Date: 25-Jan-2024 Previous Registration No:
Owner Serial No: 1 Owner Name: ROMANCH BAG
Son/Wife/Daughter of: LAXMAN BAG
Present Address: AT-REMANDA, ABANKELA, SUNDERGARH, Sundargarh, Odisha-770019
Vehicle Class: Goods Carrier Vehicle Maker: MAHINDRA & MAHINDRA LIMITED
Body Type: BULKER TANKER No of Cylinders: 6
Month/Year of Manufacturing: 8/2023
Chassis No: MA1PHARXFP6H76176 Engine No: BPBZG16554
Horse Power: 276.04 Seat(including driver): 2
Unladen Wt(kg): 14600 Laden Wt(kg): 47500
Registration Valid upto: 24-Jan-2039 Tax Amount: 8875
Tax Paid upto: 30-Jun-2024 Cubic Capacity: 7118.00
Color: WHITE YELLOW Fuel: DIESEL
Fitness upto: 24-Jan-2026 Vehicle Model: BLAZO48 HL BS6 P 67 CB
Vehicle Norms: BHARAT STAGE VI Floor Area: 0.000
Vehicle Status: Active Wheel Base: 6770
Last Change of Address done on:
Last Alteration of Vehicle done on:
2 Insurance From HDFC ERGO General Insurance Company Ltd vide policy certificate/covernote no 2315205984079000001 is valid from 28-Dec-2023 to 27-Dec-2024.
HP Details:
STATE BANK OF INDIA, SUNDERGARH, Sundargarh-770019
NOC Details:
Black List Details:
Permit Number : OR2024-GP-2923A Permit Type : Goods Permit
Permit Category :
Service Type : Select Service Type
Stand Capacity: 0 Sleep Capacity: 0
Valid from : 26-Jan-2024 Valid upto: 25-Jan-2029
Authorization Number:
Authorization Upto:
Mobile No: 6371387947
Email Id:
Particular Fee Rs. 200/- paid vide cash receipt no OR240416C8681213 dated 16-Apr-2024.
Other State/Transfer/Conversion Details
Previous Owner :
Old State :
Transfer Date :
Previous RegNo :
Entry Date :
Conversion Date :

Additional Particulars

	Number, Desc & size of	Regd. Axle Weight(in kgs)
a) Front:	10X20 PR	14000
b) Rear:	10X20 PR	33500
c) Other:	10X20 PR	0
d) Tandem:		0

Printed On: 16-Apr-2024 13:13:33

Note: This is a computer generated document. Authority Signature is not required. The document can't be used a MV document in the Vehicle.